


Notes

1. Where speed signs are incorporated in m/m board that are duplicated, the speed sign will always be nearest the road.
2. The location of signs shown on this plan may be varied slightly during implementation to improve visibility and effectiveness.
3. All redundant speed signs to be covered.
4. After installation a drive-through inspection is to be conducted and signs adjusted for maximum effectiveness.



Date: 24th September 2013 **Author:** Ron Grubb **Project:** Building of roundabout
Excell Gray Bruni: .

Comments:

- Traffic Management Plan For Roundabout at CSU Wagga Wagga
- Road closure of Valder Way
- Work To Be Conducted between 7:00am and 5.30 pm weekdays
- Plan Not Drawn To Scale. All Signage In Accordance With AS1742.3-2009

TCP prepared and Signed by,
 Ronald Grubb 5333014476

